

Report

Repair Lagging Wall Cross Duct GGH Unit.3

Location

GGH Unit.3

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

26 Feb 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

Scope of Work

- 1.Inspection
- 2.Repair Lagging
- 3.Finish

Work Procedure

- 1.Inspection
- 2.Repair Lagging
- 3.Finish



One Volts Service Co.,Ltd.

Office :

9/230 Soi Watcharapol 3, Intersestion 3,
Sub-district Khlong Thanon, District Sai Mai
Bangkok 10220 Tel: 089-488-1651

Project :	Repair Lagging	Equipment Item	GGH Unit.3
Contractor	One Volts Service Co.,Ltd.	Job Description:	Repair Lagging
Customer:	Hongsa Power Co.,Ltd	Start - Ending	21 Feb 2025



Description: Repair Lagging