

Report

***Remove and Re-installation Insulation Lagging Valve MSV.1,
MSV.2 Turbine Unit.1 Floor.3***

Location

Turbine Unit.1 Floor.3

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

23-24 Apr 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

0094 RP 94/25

Scope of Work

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**

Work Procedure

- 1.Inspection**
- 2.Remove Lagging**
- 3.Remove Insulation**
- 4.Re-Installation Insulation**
- 5.Re-Installation Lagging**
- 6.Finish**




One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	<i>Remove and Re-installation Insulation Lagging</i>	Equipment Item	<i>MSV 1 Turbine Unit.1 Floor.3</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Remove and Re-installation Insulation Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>23-25 Apr 2025</i>



Description: Remove and Re-installation Insulation Lagging



One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	<i>Remove and Re-installation Insulation Lagging</i>	Equipment Item	<i>MSV 2 Turbine Unit.1 Floor.3</i>
Contractor	<i>One Volts Service Co.,Ltd.</i>	Job Description:	<i>Remove and Re-installation Insulation Lagging</i>
Customer:	<i>Hongsa Power Co.,Ltd</i>	Start - Ending	<i>23-25 Apr 2025</i>



Description: Remove and Re-installation Insulation Lagging