

Report

***Remove and Replacement Insulation Lagging Steam Drum bi
color gauge Unit.3 Floor.7 L***

Location

Unit.3 floor.7 L

Owner

Hongsa Power

By

One Volts Service Co.,Ltd.

Work Duration

11-15 Feb 2025

<i>ContractorInspection</i>	<i>Approved</i>	<i>Commission Inspector</i>	<i>Commission Inspector</i>
..... (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>One Volts Service Co.,Ltd</i>	 (.....) <i>Hongsa Power</i>	 (.....) <i>Hongsa Power</i>

0042RP 42/24

Scope of Work

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation New Insulation
5. Installation New Lagging
6. Finish

Work Procedure

1. Inspection
2. Remove Lagging
3. Remove Insulation
4. Installation New Insulation
5. Installation New Lagging
6. Finish



One Volts Service Co.,Ltd.

Office :

32/15 Mooban The Intinity Grove (SaiMai-Pahol)
Sai Mai Road, Sai Mai Subdistrict
Bangkok 10220 Tel: 021-28007,081-3235596

Project :	Remove and ReplacementInsulation Lagging	Equipment Item	Unit.3 floor.7 L
Contractor	One Volts Service Co.,Ltd.	Job Description:	Remove and ReplacementInsulation Lagging
Customer:	Hongsa Power Co.,Ltd	Start - Ending	11-15 Feb 2025



Description: Remove and Replacement Insulation Lagging