## HONGSA POWER PLANT

**Outage Daily Report** 

2) Obstruction, Proposed solution, Required Coordination

3) Safety issues 4) Others Report by: Mr. Peerapon Nuntachai (OVS)

Issued Date : 1/11/2024

Job Tittle: ME. HSA-T3
Duration: 24 December 2023 - 16 February 2024

Yesterday: 1/10/2024	Plan%	Actual%	Today: 1/11/2024	Plan%	Actual%	Tomorrow: 1/12/2024	Plan%	Actual%
Description Activities :			Description Activities :			Description Activities :		
FGD			FGD			FGD		
Expansion Joint Size 6,110x15,700x350mm> Clean Gas Outlet			Expansion Joint Size 6,110x15,700x350mm> Clean Gas Outlet			Expansion Joint Size 6,110x15,700x350mm> Clean Gas Outlet		
Installation Coating	Wait		Installation Coating	Wait		Installation Coating	Wait	
Expansion Joint Size 6,110x15,700x350mm> Clean Gas Inlet			Expansion Joint Size 6,110x15,700x350mm> Clean Gas Inlet			Expansion Joint Size 6,110x15,700x350mm> Clean Gas Inlet		
Installation Coating	Wait		Installation Coating	Wait		Installation Coating	Wait	
Expansion Joint Size 6,110x15,700x350mm> Flue Gas Inlet			Expansion Joint Size 6,110x15,700x350mm> Flue Gas Inlet			Expansion Joint Size 6,110x15,700x350mm> Flue Gas Inlet		
Remove Expansion Joint Belt	100%	100%	Installation Expansion Joint Belt	50%	50%	Installation Expansion Joint Belt	100%	
Test:			Test:			Test:		
Obstruction :			Obstruction :			Obstruction :		
Proposed Solution :			Proposed Solution :			Proposed Solution :		
Overall Work Progress: 75 %			Overall Work Progress: 75 %			Overall Work Progress:%		
Ahead of Sch. ( days), On Sch., Delay from Sch. ( days)			Ahead of Sch. (days),On Sch.,Delay from Sch. (days)			Ahead of Sch. ( days), On Sch., Delay from Sch. ( days)		
Recovery Action :			Recovery Action :			Recovery Action :		
Total Manpower: OVS. 27 Sub. 0			Total Manpower: OVS. 27 Sub. 0			Total Manpower: OVS. 27 Sub. 0		
Accident & Injury : None			Accident & Injury: None			Accident & Injury: None		
Dailt meeting agenda: 1) Yesterday work done, Today work to be done, Progress, Tomorrow work to be done								