



Daily Report

Job name: Expansion Joint Clean Gas Inlet

Description: Installation Expansion Joint Frame 80 %

Picture



Remark:




Date: 03/01/2024

Daily Report

Job name: Expansion Joint Clean Gas Outlet

Description: Installation Expansion Joint Frame 40%

Picture



Remark:


Date: 03/01/2024

Daily Report

Job name: Expansion Joint Outlet BUF

Description: Remove Insulation and Expansion Joint Belt เสร็จเรียบร้อยยกเว้น

Picture



Remark:

Date: 03/01/2024