

# Daily Report

**Job name:** Expansion Joint Flue Gas Outlet

**Description:** Cleaning Expansion Joint Frame 100%

**Picture**



**Remark:**

**Date:** 09/01/2024

# Daily Report

**Job name:** Expansion Joint BUF Outlet

**Description:** Cleaning Expansion Joint Frame 100%

**Picture**



Remark:


Date: 09/01/2024



**Job name:** Expansion Joint Inlet ESP No.2

**Description:** Remove Expansion Joint Belt 100%

**Picture**



**Remark:** ตรวจพบจุดรั่วของ Liner 1 จุด


**Date:** 09/01/2024

# Daily Report

**Job name:** Expansion Joint Inlet ESP No.6

**Description:** Remove Expansion Joint Belt 100%

**Picture**



**Remark:**

**Date: 09/01/2024**