

Daily Report

Job name: Expansion Joint Clean Gas Inlet

Description: Installation Insulation and Lagging 100%

Picture



Remark:


Date: 13/02/2024

Daily Report

Job name: Expansion Joint Clean Gas Outlet

Description: Installation Insulation and Lagging 100%

Picture



Remark:

Date: 13/02/2024

Daily Report

Job name: Expansion Joint Outlet ID Fan A

Description: Installation Insulation and Lagging 100%

Picture



Remark:

Date: 13/02/2024