


Daily Report

Job name: Expansion Joint Outlet BUF

Description: Installation Expansion Joint Belt 80%

Picture



Remark:

Date: 18/01/2024

Job name: Expansion Joint Low Leakage Fan Outlet

Description: Installation Expansion Joint Belt 100%

Picture



Remark:

Date: 18/01/2024

Daily Report

Job name: Expansion Joint Absorber Outlet to Clean Gas

Description: Installation Expansion Joint Frame 70%

Picture



Remark:

Date: 18/01/2024

Daily Report

Job name: Expansion Joint Outlet Clean Gas

Description: Installation Liner 90%

Picture



Remark:


Date: 18/01/2024

Daily Report

Job name: Expansion Joint Inlet ESP No.2

Description: Installation Liner 100%

Picture



Remark:

Date: 18/01/2024

Daily Report

Job name: Expansion Joint Inlet ESP No.6

Description: Installation Liner 100%

Picture



Remark:

Date: 18/01/2024