

Daily Report

Job name: Expansion Joint Outlet BUF

Description: Installation Insulation Lagging 80%

Picture



Remark:

Date: 20/01/2024

Daily Report

Job name: Expansion Joint Absorber Outlet to Clean Gas

Description: Installation Expansion Joint Frame 80%

Picture



Remark:


Date: 20/01/2024

Daily Report

ob name: Expansion Joint Inlet ESP No.2

Description: Installation Expansion Joint Belt 50%

Picture



Remark:


Date: 20/01/2024

Daily Report

Job name: Expansion Joint Inlet ESP No.6

Description: Installation Expansion Joint Belt 50%

Picture



Remark:

Date: 20/01/2024