


Daily Report

Job name: Expansion Joint Absorber Outlet to Clean Gas

Description: Installation Expansion Joint Frame 100%

Picture



Remark:



Date: 23/01/2024

Daily Report

Job name: Expansion Joint Outlet ID Fan A

Description: Remove Expansion Joint Belt 50%

Picture



Remark:

Date: 23/01/2024