


Daily Report

Job name: Expansion Joint Clean Gas Outlet

Description: Remove Expansion Joint Frame

Picture



Remark:

Date: 26/12/2023

Daily Report

Job name: Expansion Joint Booster Fan A

Description: Remove Insulation Lagging and Expansion Joint Belt

Picture



Remark:

Date: 26/12/2023

Daily Report

Job name: Expansion Joint Booster Fan B

Description: Remove Insulation Lagging and Expansion Joint Belt

Picture



Remark:

Date: 26/12/2023