

Job name: Fabrication CGF B , Low leakage Fan inlet Expansion joint Unit 2

Description: Repair Expansion joint
- Replacement CGF B , Low leakage fan Inlet

Picture



Remark:

Date: 17/10/2023



OVS Daily Report

One Volts Service Co.,Ltd.
9/230 Soi Watcharapol 3 Intersection 3
Sub-district Klong Thanon District Sai Mai
Bangkok 10220 Tel:089-488-1651

Job name: Fabrication CGF B , Low leakage Fan inlet Expansion joint Unit 2

Description: Repair Expansion joint
- Replacement CGF B , Low leakage fan Inlet

Picture



Remark:

Date: 17/10/2023