

Job name: Inspection Cold Gas Fan B Expansion joint Unit 2

Description: Cold Gas Fan B Expansion joint

- ตรวจสอบสภาพความเสียหายของ Fabric Expansion joint



Remark:

Date: 12/10/2023