



Job name: Inspection Cold Gas Fan B Expansion joint Unit 1

Description: Cold Gas Fan B Expansion joint

- ตรวจสอบสภาพความเสียหายของ Fabric Expansion joint

Picture



Remark:

Date: 18/08/2023