

Job name: Expansion Joint Absorber Tank Outlet

Description: Installation Expansion Joint

Picture



Remark: Finish

Date: 15/02/2025

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220
Tel : 089-4881651
E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint IDF Outlet 3A	
Description: Inspection In Size Expansion Joint	
Picture	
	
	
Remark: ได้เข้าตรวจสอบด้านในของ Expansion Joint IDF Outlet 3A ด้านในปกติ	
Date: 15/02/2025	

Job name: Expansion Joint IDF 3B	
Description: Inspection In Size Expansion Joint	
Picture	
	
	
Remark: ได้เข้าตรวจสอบด้านในของ Expansion Joint IDF Outlet 3A ด้านในปกติ	
Date: 15/02/2025	