

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220

Tel : 089-4881651

E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct IDF A to Duct IDF B	
Picture	
	
	
	
Remark: ตรวจสอบ Expansion Joint ด้านในตรวจพบด้านบนของ Expansion Joint รั่ว 1 จุดและด้านนอกตรวจพบ Insulation Lagging เสียหาย	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220
Tel : 089-4881651
E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct By Pass to Cold Gas Fan A	
Picture	
	
	
ตรวจสอบ Expansion Joint ทั้งด้านในและด้านนอกปกติ	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220

Tel : 089-4881651


E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct By Pass to Cold Gas Fan B	
Picture	
	
	
ตรวจสอบ Expansion Joint ทั้งด้านในและด้านนอกปกติ	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220
Tel : 089-4881651
E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct By Pass to Stack No.1	
Picture	
	
	
ตรวจสอบ Expansion Joint ทั้งด้านในและด้านนอกปกติ	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220
Tel : 089-4881651
E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct By Pass to Stack No.2	
Picture	
	
	
	
ตรวจสอบ Expansion Joint ด้านนอกปกติและด้านในตรวจพบ Linerบริเวณด้านล่างเสียหาย 2 จุด	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.


32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220
Tel : 089-4881651
E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct By Pass to Stack No.3	
Picture	
	
	
	
ตรวจสอบ Expansion Joint ด้านนอกปกติและด้านในตรวจพบ Liner บริเวณด้านล่างเสียหาย 2 จุด	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220
Tel : 089-4881651
E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct By Pass to BUF A	
Picture	
	
	
ตรวจสอบ Expansion Joint ด้านนอกปกติและด้านในตรวจพบ Liner บริเวณด้านล่างเสียหายหลายจุด	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220

Tel : 089-4881651

E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint Duct IDF to By pass	
Description: Inspection Expansion Joint Duct By Pass to BUF A	
Picture	
	
	
ตรวจสอบ Expansion Joint ทั้งด้านในและด้านนอกปกติ	
Date: 20/02/2025	

Daily Report

One Volts Service Co.,Ltd.

32/15 Mooban The Intinity Grove(SaiMai-Pahol),
Sai Mai Road, Sai Mai Subdistrict Bangkok 10220
Tel : 089-4881651
E-mail : khegwannapa@yahoo.com

Job name: Expansion Joint FGD	
Description: Inspection Expansion Joint Clean Gas Inlet	
Picture	
	
	
ตรวจสอบ Expansion Joint ทั้งด้านในและด้านนอกปกติ	
Date: 20/02/2025	