

Daily Report	Ex.joint Team	วันที่ 25.7.2023
Location:	FGD Unit1	
Description	Remove Expansion joint Low leakage Fan Outlet 14:30-16:20	
		
Remark		