

ISO: 45001 One Volts Service Co.,Ltd Safety Performance

31 March 2023

Monthly Performance Update





5.3 Corporate Safety Division

(Safety Power Plant)

One Volts Service Co.,Ltd.


Organization Chart Site Office in Hongsa Project



ONE VOLTS SERVICE COMPANY LIMITED

9/230 SOI WATCHARAPOL 3, YAEK 3, KHLONGTANON, SAIMAI BANGKOK 10220 Tel: 0894881651, Email: khegwannapa@yahoo.com

Organization Chart



HONGSA POWER



SAFETY SLOGAN













Mi state illi





Mr. and M.



นโยบายด้านความปลอดภัย



บริษัท วันโวลด์ เซอร์วิส จำกัด ONE VOLTS SERVICE COMPANY LIMITED

9/230 หมู่ 4 แขวงคลองถนน เขตสายใหม กรุงเทพมหานคร 10220









นโยบายความปลอดภัย อาชีวอนามัยและสภาพแวดล้อมในการทำงาน

บริษัท วันโวลต์ เชอร์วิส จำกัด

บริษัท วันไวลด์ เซอร์วิส จำกัด ได้มีการจัดการของเรื่องความปลอดภัย อาชีวอนามัย และสิ่งแวดล้อมในการทำงานที่ดีและได้คุณภาพ โดยทำการนำระบบมาตรฐานด้านความปลอดภัย อาชีวอนามัย และสิ่งแวดล้อมในการทำงาน มาเข้าระบบการทำงานมีดังนี้

- 1. ปฏิบัติตามกฎหมายและซ้อกำหมดต่างๆ ด้านความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน
- ป้องกันการเกิดอุบัติเหตุ การเจ็บป่วยจากการทำงานของพนักงานทุกระศับชั้น จากการดำเนินกิจการของบริษัท
 ฉดการสูญเสีย การเกิดอุบัติเหตุ อันตรายต่างๆ ที่เกิดจากการทำงานและบริเวณโดยรอบ
- 4. ปรับปรุงแก้ไขข้อบกพร่อง ให้ได้มาตรฐานด้านความปลอดภัย อชีวอนามัย และสิ่งแวดล้อมในการทำงานของบริษัทอย่างต่อเนื่อง



POWER PLANT SAFETY PERFORMANCE YEAR 2022



One Volts Service Co.,Ltd.

Man-Hour /Month	Jan	Feb	Mar	Apr	May	Jun	July	Aug	Sep	Oct	Nov	Dec	Total
Manpower	42	44	44	43									-
Working Hours	960	1,006	1,095	1,032									4,093

..... We are here

Working Hours W/H LTI Target 2023

Power Plant


: 15.0 Million (5 Feb 21 - 25 Dec 2023)

Working Hours W/H LTI Actual

- Working Hours in March '23: 4,093 Hours
- Total Working Hours without LTI Y2023 : 4,093 Hours
- Best Record W/H LTI: 146,592 Hours
 (26 Dec 21 25 April 23)

One Volts Service Co.,Ltd ACCIDENT PYRAMID 2022





One Volts Service Co.,Ltd ACCIDENT in December 2022





No Accident of this Month









Implement Effectiveness

Safety role model

Safety sign layout in power plant area (In the installation phase)

Review and analyze risk assessment to complete all activity and section Set up report plan and follow up and review data from contractor for

ISO45001 together with advise contractor about topic as required

Review SPR 9 report, JSA 33 reported And PWRA 45 reported.

Set up safety officer organization in executive and supervisory level for power plant

A Awareness

Contractor participate to report UA, UC and near miss

Following submission of House keeping everyday and weekly activity. activity in power plant

M Mindset

Safety officer of contractor checked wearing PPE of team before entry of power plant and everyone cooperate very well

C Commitment

Safety slogan & safety key message in the meeting

Working hours without LTI target:
12,000,000 hours (Continuous) / 8,100,000 hours (Year 2022)

Communication

COVID-19 Control measures in plant.

Safety talk in small group of each contractor before starting a job

Weekly SHE contractor meeting 18 times

Promote Stop and Thinks card and steel poster 10

Competency

Update training record of HPC power plant

Weekly Exercise fire fighting team

Refreshment General safety for contractor 7/15 Class



Implement Effectiveness

- Safety sign layout in power plant area (In the installation phase)
- Review and analyze risk assessment to complete all activity and section
- Review SPR report, JSA reported And PWRA reported.
- Set up safety officer organization in executive and supervisory level for power plant











A

Awareness

- Staff body temperature measurement
- Staff Alcohol measurement
- Strengthen Safety Performance












C

Communication

- Safety talk in small group of each staffs before starting a job
- Sharing SHES MOMENT OF April '2023 (How to protect yourself during earthquake) to staffs.

















A Awareness

 \triangle

Primary Therapy


 \subseteq

First Aid













Annual Health Check.



















Strengthen Safety Performance

Monthly Drug Testing Course







Awareness

- Contractor participate to report UA, UC and near miss
- Monthly Inspection of Electrical Equipment
- Fire extinguisher checking










Α

Awareness

- Contractor participate to report UA, UC and near miss
- Assess the risks before starting work Using PWRA



ń		สังเคาาะเพื่อในขึ้น					ใช้เรื่องกับหรือการคุณกับความที่เกิดขึ้น C E				
- the second of			:	- ชากการ์ ก - อำนา ซี ออ ยาก - ปุจุทรัง pos Leadin				### ##################################			
หมายเหตุ: C (Control) คือ ได้คืนในอนุญายกำนาแก้ว อะชื่ออกอใน Red Top Moner Int	Z N	ne limen	อง จัดก็บาย:	ate) คือ ค่าจัดอับผ ผลานทำความสวด อัคบ้ำอรั้งและว่าในที่เก	าดพื้นในอนุ	daunin p		ishir dheadin	rar Basmunuans Jo	□ Nider	
ตัวรักกิกกใน Red Tag Muser แล้ ช้ายภูปกรณ์ต่างๆ ออกจาทั้นที่แล้		lines			□ #	-	tsinfersion		□ N	D Nich	
กระกองชื่อทุกคนที่สามานในพื้น	ก่อนสัมภาก	40gqou	M. Son	in P				(ด้วยน้ำมน)	Mr. Southerne	No si	
	เผลงวักร	เร้า บ่าย เ	6 \$ 0		หลามัคร	000000			YOUTERAYORS		





Safety officer of contractor checked wearing PPE of team before entry of power plant and everyone cooperate very well

Safety role model















Communication



COVID-19 Control measures - social distancing



Safety talk in small group of each staffs before



Sharing SHES MOMENT OF November'2022 (How to



protect yourself during earthquake) to staffs.



Attend Weekly SHE contractor meeting









One Volts Service Co.,Ltd.



A Awareness

- Contractor participate to report UA, UC and near miss
- Following submission of House keeping everyday and weekly activity. activity in power plant



◆田台田台 (11,台会会。(1)









Update training record of One Volts Service Co.,Ltd

General safety training, Report Problems, Obstacles and Fix various Obstacles

Attend the Psychosocial Risk Assessment training









Competency



Update training record of One Volts Service Co.,Ltd



General safety training, Report Problems, Obstacles and Fix various Obstacles



Attend the Psychosocial Risk Assessment training







Difficulty and area of concerned



Key Progress	Difficulties & Concerns	Resolution	Target Date	PIC*-
- Insulation Lagging and Expension Joint.	- Dust Particles and Glass fiber fragments (Respiratory hazards).	 wearing 3M mask while working. Refreshment of work procedure to staffs. House keeping everyday and weekly activity. watering around working area. 	Continual communicati on 2023	One Volts Service Co.,Ltd Safety



One Volts Service Co.,Ltd Thank You