

One Volts Service Co.,Ltd SAFETY PERFORMANCE

31 January 2023



ISO: 45001 One Volts Service Co.,Ltd Safety Performance

31 January 2023

Monthly Performance Update





5.3 Corporate Safety Division

(Safety Power Plant)

One Volts Service Co.,Ltd.


Organization Chart Site Office in Hongsa Project



ONE VOLTS SERVICE COMPANY LIMITED

9/230 SOI WATCHARAPOL 3, YAEK 3, KHLONGTANON, SAIMAI BANGKOK 10220 Tel : 0894881651, Email : khegwannapa@yahoo.com

Organization Chart



HONGSA POWER



SAFETY SLOGAN













Mi state illi

นโยบายด้านความปลอดภัย



บริษัท วันโวลด์ เซอร์วิส จำกัด ONE VOLTS SERVICE COMPANY LIMITED

9/230 หมู่ 4 แขวงคลองถนน เขตสายใหม กรุงเทพมหานคร 10220







นโยบายความปลอดภัย อาชีวอนามัยและสภาพแวดล้อมในการทำงาน

บริษัท วันโวลต์ เชอร์วิส จำกัด

บริษัท วันไวลด์ เชอร์วิส จำกัด ได้มีการจัดการของเรื่องความปลอดภัย อาชีวอนามัย และสิ่งแวดล้อมในการทำงานที่ดีและได้คุณภาพ โดยทำการนำระบบมาตรฐานด้านความปลอดภัย อาชีวอนามัย และสิ่งแวดล้อมในการทำงาน มาเข้าระบบการทำงานมีดังนี้

- 1. ปฏิบัติตามกฎหมายและซ้อกำหมดต่างๆ ด้านความปลอดภัย อาชีวอนามัย และสภาพแวดล้อมในการทำงาน
- ป้องกันการเกิดอุบัติเหตุ การเจ็บป่วยจากการทำงานของพนักงานทุกระดับชั้น จากการดำเนินกิจการของบริษัท
 ฉดการสูญเสีย การเกิดอุบัติเหตุ อันตรายต่างๆ ที่เกิดจากการทำงานและบริเวณโดยรอบ
- 4. ปรับปรุงแก้ไขข้อบกพร่อง ให้ได้มาตรฐานด้านความปลอดภัย อชีวอนามัย และสิ่งแวดล้อมในการทำงานของบริษัทอย่างต่อเนื่อง



POWER PLANT SAFETY PERFORMANCE YEAR 2022



One Volts Service Co.,Ltd.

Man-Hour /Month	Jan	Feb	Mar	Apr	May	Jun	July	Aug	Sep	Oct	Nov	Dec	Total
Manpower	42												-
Working Hours	966												54,600

We are here

Working Hours W/H LTI Target 2023

Power Plant

: 12.0 Million Hours (5 Feb 21 - 25 Dec 22)

Working Hours W/H LTI Actual

- Working Hours in July '22 : **7,872** Hours
- Total Working Hours without LTI Y2022 : *54,600* Hours
- Best Record W/H LTI : 146,592 Hours

(5 Feb 21 - 25 June 22)








One Volts Service Co.,Ltd ACCIDENT PYRAMID 2022





One Volts Service Co.,Ltd ACCIDENT in December 2022





No Accident of this Month



Implement Effectiveness

Safety role model

Safety sign layout in power plant area (In the installation phase)

Review and analyze risk assessment to complete all activity and section Set up report plan and follow up and review data from contractor for ISO45001 together with advise contractor about topic as required

Review SPR 9 report, JSA 33 reported And PWRA 45 reported.

Set up safety officer organization in executive and supervisory level for power plant

A Awareness

Contractor participate to report UA, UC and near miss

Following submission of House keeping everyday and weekly activity. activity in power plant

M Mindset

Safety officer of contractor checked wearing PPE of team before entry of power plant and everyone cooperate very well

C Commitment

Safety slogan & safety key message in the meeting

Working hours without LTI target:
12,000,000 hours (Continuous) / 8,100,000 hours (Year 2022)

Communication

COVID-19 Control measures in plant.

Safety talk in small group of each contractor before starting a job

Weekly SHE contractor meeting 18 times

Promote Stop and Thinks card and steel poster 10

Competency

Update training record of HPC power plant

Weekly Exercise fire fighting team

Refreshment General safety for contractor 7/15 Class





Communication

COVID-19 Control measures - social distancing

Safety talk in small group of each staffs before starting a job

Sharing SHES MOMENT OF JULY'2022 (How to

protect yourself during earthquake) to staffs.

Attend Safety weekly meeting











Awareness

区区

Contractor participate to report UA, UC and near miss

Following submission of House keeping everyday and weekly activity. activity

in power plant

 \subseteq

Staff body temperature measurement

 \square

Antigen Test Kit (ATK)

~









Awareness

区

Contractor participate to report UA, UC and near miss

Following submission of House keeping everyday and weekly activity. activity in power plant

[]

Staff body temperature measurement

 \subseteq

Antigen Test Kit (ATK)

 $\mathbf{\Sigma}$









A Awareness

 \triangle

Primary Therapy

 \subseteq

First Aid











Annual Health Check.

















A Awareness

Strengthen Safety Perfornance

Montly Drung Testing Course







Awareness

 \subseteq

Contractor participate to report UA, UC and near miss

ſ√.

Following submission of House keeping everyday and weekly activity. activity

in power plant

 $\mathbf{\Sigma}$

Staff body temperature measurement

 \leq

Antigen Test Kit (ATK)

 \square









A

Awareness

 \subseteq

Contractor participate to report UA, UC and near miss

Following submission of House keeping everyday and weekly activity. activity

in power plant

 \subseteq

Staff body temperature measurement

 \subseteq

Antigen Test Kit (ATK)

 $oldsymbol{\subseteq}$








A Awareness

Contractor participate to report UA, UC and near miss

Following submission of House keeping everyday and weekly activity. activity in power plant

Staff body temperature measurement

Antigen Test Kit (ATK)



					กรประเทิงความ	NWD 100 MU LH JY	H21M)		
Tennustridazia			discontinues.		Minutes	Ministration repulses whilefu C E			
- MANNELL TO AN AN - MORE TOUR POR MANNEY SHEET WAT OR COMMENT OF THE MANNEY SHEET WAT OF THE MANNEY W	dios daja dios daja	V	- 3/4°	กกุ พื้อ 2 อธิ ยาก ขกับ pa: ไ	Fn dfW	- 96 5	Body Harrisos. 3 mags. 16 19 20 Mr. 189292.		
MINISTREE C (Control) Re insuesidant	ne			กำรักสับครายออก เพราะเสราคเพื่อใ		Secretain discasi	nos wazwanosi ran		
and the state of the	-								
	D 20/6	07600 G	induser ladies	maritulists Z	to taken	Sac	DH	C) Nife	
Military greature of 19	D hide		indones indoné		to □ today		D.H.	D 16	
nessnoonly Red Tag Moore of 1		12501	indusec ลิสปาส			das		D W	
อะรีกอกกใน Red Tay Master เครื่ว 🌐 ให้ ท็อกูปกรณ์ที่ระวุ ออกจะพื้นที่เอริว 🔲 ให้	□ túde	17501 17501		0	te today	das		0 16	
อะชื่อออกใน Red Tay Masser เก็ว วิจั รับอุปกรณ์ล่างๆ ออกจาที่เก็บอัว วิจั วูนะ อะชื่อถูกคนที่สำราช ในพัน (ก่อนสิ้นสาน)	□ túde	rios M	inform instart	0	te texter	รัลง (หัวพร้ายน) ส่ว จิล	DW	0 16	
องที่ของอยใน Red Top Monor หลัว 📋 ให้ ก็ของปกรณ์ด้วยๆ ของคงาที่เกล็กสั่ว 📋 ให้ ของของที่สามานาโกรัน (ก่อนเป็นขาก) ซื้อ พมระเพลิก	□ lide □ lide fagitau	rios M	r. Sentin af		to tasker	รัลง เพิ่าหน้าเกม ซึ่ง ซื้อ	Nr. sorthere	0 16	
orknoonly Red Tay Monor off 16 fingular sides y constitution 16 ya sa rhaqonovida resultatia (riendustru) fin sustantini	□ lide □ lide fagitau	PA Ma	r. Sentin af		te today	(6) \$40 (6) 100 \$100 \$100 \$100 \$100 \$100 \$100 \$100	Nr. sorthere	0 16	
orknoonly Red Tay Monor off 16 fingular sides y constitution 16 ya sa rhaqonovida resultatia (riendustru) fin sustantini	□ lide □ lide fagitau	- M	r. Sentin af		te texter	dise riser (filmsissus)	Nr. sorthere	#h :	
orknoonly Red Tay Monor off 16 fingular sides y constitution 16 ya sa rhaqonovida resultatia (riendustru) fin sustantini	□ lide □ lide fagitau	- M	r. Sentin af		te today	dise riser (filmsissus)	Nr. sorthere	0 16	
orknoonly Red Tay Monor off 16 fingular sides y constitution 16 ya sa rhaqonovida resultatia (riendustru) fin sustantini	□ lide □ lide fagitau	IM in	r. Sentin af		te texter	Size (Size Size Size Size Size Size Size Size	Nr. sorthere	#h :	
องข้อออกใน Red Tay Muser เก็ว วิจั สำอรูปกรณ์ทำวร ออกจาที่เก็บเอ็ว วิจั เรอง เองข้ออุกทรเท็สโรงาน ในเป็น (ก่อนเป็นสาน)	toffen	- M	r. Sentin af		te toder	Size (Size Size Size Size Size Size Size Size	Nr. sorthere	#h :	





Safety officer of contractor checked wearing PPE of team before entry of power plant and everyone cooperate very well

Safety role model















Communication

COVID-19 Control measures - social distancing

 \square

Safety talk in small group of each staffs before

starting a job

Sharing SHES MOMENT OF November'2022 (How to

V

protect yourself during earthquake) to staffs.

S

Attend Weekly SHE contractor meeting











A

Awareness

区区

Contractor participate to report UA, UC and near miss

Following submission of House keeping everyday and weekly activity. activity

in power plant

 \subseteq

Staff body temperature measurement

 \subseteq

Antigen Test Kit (ATK)

 \square











Update training record of One Volts Service Co.,Ltd

General safety training, Report Problems, Obstacles and Fix various Obstacles

Attend the Psychosocial Risk Assessment training









Competency



Update training record of One Volts Service Co.,Ltd



General safety training, Report Problems, Obstacles and Fix various Obstacles



Attend the Psychosocial Risk Assessment training











 \triangle

Update training record of One Volts Service Co.,Ltd

General safety training, Report Problems, Obstacles and Fix various Obstacles

Attend the Psychosocial Risk Assessment training

SHE Internal Audit ISO: 14001 ISO: 45001









Difficulty and area of concerned



Key Progress	Difficulties & Concerns	Resolution	Target Date	PIC*-
- Insulation Lagging and Expension Joint.	- Dust Particles and Glass fiber fragments (Respiratory hazards).	 wearing 3M mask while working. Refreshment of work procedure to staffs. House keeping everyday and weekly activity. watering around working area. 	Continual communicati on 2023	One Volts Service Co.,Ltd Safety